

*flex*KRETE

WORLD'S BEST CONCRETE REPAIR PRODUCT

Using their tusks, Elephants at the Kansas City Zoo dug into failed concrete at the joint, increasing the size of the void. Contractors used FlexKRETE's fast-set material to repair the damage and provided a long-term solution for securing this section of the habitat's enclosure quickly and economically.

Elephants VS FlexKRETE

It was a challenge but FlexKRETE wins the day in KC.



Imagine this phone call; "Hello, this is The Kansas City Zoo and the elephants keep destroying a concrete wall. Can you help?". That might not be the exact conversation Bob Kobush's team at [Pro's Choice Concrete Products](#) had with the caller, but it's definitely a problem they solved using FlexKRETE Superior Concrete Repair Material.

The above image includes four pictures; two before and two after. From left to right; un-prepped area before, cut-out prepped area before, full-length after, and a close-up of tooled FlexKRETE after.

Prior to FlexKRETE, other repair materials were used but failed quickly. The elephants kept returning and succeeding in tearing apart the wall. FlexKRETE withstands extreme abuse and won't crack or pop out - even when in vertical applications where elephants repeatedly attempt to damage the structure.
